



NOTES: 1) PARALLEL ACT, COM, SAF FOR PAIR DOORS. OR MAY REQUIRE HORTON C7215 SIMULTANEOUS ACTIVATION MODULE. CONTACT BEA TECH SUPPORT FOR MORE INFO IF NECESSARY

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM

BEA
 We open up New Horizons
 HANNA GROUP
 100 ENTERPRISE DRIVE
 PITTSBURGH, PA 15275
 PHONE: (412) 249-4100
 FAX: (412) 249-4101
 EMAIL: www.beasensors.com

TITLE: HORTON C4160-2 CONTROL WITH PARALLAX 2 SYSTEM (LO21B/U), SAFETY SIDE SUPERCAN INHIBIT RELAY

SIZE: B	DRAWN BY: KJG	REV BY: WJR	PART NO: 80.0095.03
SCALE: NONE	DATE: 10 SEPT. 2008	SHEET: 1 OF 1	