



- NOTES:
1. EAGLE SENSORS ARE USED FOR SECONDARY ACTIVATION ONLY AND WILL NOT ALLOW ACTIVATION WHEN DOOR IS FULLY CLOSED.
 2. QUADSCANS CAN BE PLUGGED INTO EITHER CONNECTOR. HOWEVER, QUADSCAN DOOR 1 RELATES TO STALL 1 INPUT. QUADSCAN DOOR 2 RELATES TO STALL 2 INPUT. EACH INPUT HANDLES THE ACTIVATION AND STALL FOR THE RESPECTIVE DOOR.
 3. IF A SECOND BODYGUARD IS REQUIRED, USE A "Y" HARNESS (20.5083).
 4. THE KNOWING ACT SWITCH IS CONNECTED AT THE AUX INPUT AND CAN BE ANY DRY CONTACT DEVICE SUCH AS A PUSHPLATE, CARD READER, ETC. THE AUX INPUT IS REQUIRED FOR ALL INITIAL ACTIVATION WHEN FUNCTION FA ON THE MP HUB IS SET TO '01'.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

BEA 100 ENTERPRISE DRIVE
 PITTSBURGH, PA 15275
 PHONE: (412) 249-4100
 FAX: (412) 249-4101
 EMAIL: www.beasensors.com

**TITLE: MP HUB WITH PASSPORT PLUS
 DOUBLE-EGRESS PACKAGE WITH
 KNOWING ACT**

SIZE: A	DRAWN BY: KJG	REV BY: TUC	PART NO: 80.0238.00
	SCALE: NONE	DATE: 22 NOV 2005	SHEET 1 OF 1