



NOTES: 1) TO INSURE ANSI COMPLIANCE, SUPER SCANS MUST BE USED IN CONJUNCTION W/ BODY GUARD AND LO21 SERIES LOCK OUT MODULE. REFER TO APPROPRIATE LO21 SERIES LOCK OUT MODULE USERS GUIDE FOR PROPER WIRING OF BODYGUARD AND LOCK OUT.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

100 ENTERPRISE DRIVE
PITTSBURGH, PA 15275
PHONE: (412) 249-4100
FAX: (412) 249-4101
EMAIL: www.beasensors.com

**TITLE: HORTON 4160 WITH
SUPPERSCAN RELAY HARNESS**

| | | | |
|--------|-------------|---------|------------|
| SIZE: | DRAWN BY: | REV BY: | PART NO: |
| B | WJR | | 80.0393.00 |
| SCALE: | DATE: | SHEET | |
| NONE | 20 OCT 2014 | 1 OF 1 | |